

- <sup>①</sup> FHWA Assigned Load Rating Memo, Dated 09/29/2011, and Chapter 6, TxDOT BIM
- <sup>2</sup> Section 1 Chapter 6, TxDOT Bridge Inspection Manual
- <sup>③</sup> Old TBLRP (ASD) load ratings performed after 2011 shall not be concurred for steel or concrete components.
- <sup>(4)</sup> Send an email to LR\_Needed@txdot.gov. Start the subject line with "Missing AASHTO TYPE 3 and NRL rating factors NBI#"
- (5) Section of "Concrete Box Culvert Load Rating by Design Load Correlation" in Chapter 6, TxDOT BIM.
- <sup>®</sup> If a concrete box culvert bridge has an expansion slab or it contains non-culvert units, those non-culvert units shall be evaluated by the most applicable of the three load rating methods: Assigned, Assumed, or Calculated ratings. Report the controlling load rating.
- To rexample, if inventory rating is assumed to be HS15 (RF=0.75) and operating rating is assumed to be HS20 (RF=1.00), AASHTO Type 3 Trucks, NRL, SHV and EV operating rating factors shall be 1.00. If inventory rating is assumed to be HS10 (RF=0.50) and operating rating is assumed to be HS15 (RF=0.75), AASHTO Type 3 Trucks, NRL, SHV and EV operating rating factors shall be 0.75.
- <sup>®</sup> If a routine inspection team is not capable of performing a load rating due to complexity of the bridge, send an email to LR\_Needed@txdot.gov. Start the subject line with "LR Needed NBI#"