

AGENDA

TEXAS TRANSPORTATION COMMISSION 125 East 11th Street Austin, Texas

WEDNESDAY January 17, 2024

NOTE:

Persons with special needs or disabilities who require auxiliary aids or services are requested to contact Amanda Brown at (512) 550-7025 at least three working days before the day of the meeting so that appropriate arrangements can be made.

Atención. Si desea recibir asistencia gratuita para traducir esta información, llame al 512-305-9500.

10:00 A.M. **CONVENE MEETING**

1. **Safety Briefing**

Staff will provide general safety instruction.

2. **Opening Comments from Commissioners and Executive Director**

- Commissioner Steven D. Alvis a.
- **Commissioner Alex Meade** b.
- c. Commissioner Robert C. Vaughn
- Commissioner Alvin New Texas Freight Advisory Committee d.
- Chairman J. Bruce Bugg, Jr. e.
- Executive Director Marc Williams f.
- 3. Consider the approval of the Minutes of the December 12, 2023, regular meeting of the Texas **Transportation Commission**

4. **Contracts**

1

Consider the award or rejection of contracts for highway construction and maintenance, and construction and rehabilitation of buildings (Presentation)

These proposed minute orders contain information concerning the receipt of bids for highway improvement contracts. The department may reschedule receipt of bids for those projects where the commission rejects all bids. Those bids accepted by the commission will result in conditional contract awards to the low bidders. Contract award conditions may involve securing funding from other sources, the contractor's ability to satisfy federal DBE subcontracting requirements, or other requirements as outlined in the project bid proposal.

116622	a.	Highway Improvements and Other Transportation Facilities (MO)
		(see attached itemized list)
116623	b.	Routine Maintenance (MO)
		(see attached itemized list)
116624	с.	Construction and Rehabilitation of Buildings (MO)

Construction and Rehabilitation of Buildings (MO) (see attached itemized list)

5. Discussion Item

Development of the 2025 Unified Transportation Program (UTP) Planning Targets (<u>Presentation</u>)

The Unified Transportation Program (UTP) is a 10-year statewide plan for transportation project development. The purpose of this presentation is to facilitate a discussion of the 2025 UTP planning targets and investment strategy. The outcome will be a guidance document to be distributed to department districts, metropolitan planning organizations, and other planning partners for the development of the 2025 UTP.

6. Aviation

Various Counties - Consider the award of federal non-primary entitlement grant funding, federal apportionment grant funding and state grant funding for airport improvement projects at various locations (MO)

Federal law authorizes the award of federal non-primary entitlement grant funding and federal apportionment grant funding to preserve and improve the state's general aviation system. State law authorizes the award of state grant funding for capital improvement projects.

7. **Transportation Corporation**

Galveston and Brazoria Counties - Designate a portion of Segment B of the SH 99 (Grand Parkway) toll project (Segment B-1) as a toll project on the state highway system; authorize the Grand Parkway Transportation Corporation (GPTC) to act on behalf of the commission in connection with the development, financing, refinancing, design, construction, reconstruction, expansion, tolling, operation and maintenance of Segment B-1 in Galveston and Brazoria counties; authorize GPTC to enter into, assign and assume all contracts relating to Segment B-1 and perform any function necessary to the exercise of powers delegated to GPTC; authorize amendments to the toll rate agreement between the commission and GPTC to include Segment B-1; authorize the executive director of the department to execute a project agreement with GPTC to provide for the allocation of responsibilities relating to Segment B-1; and provide for the assignment of revenues of Segment B-1 to GPTC (MO)

In Minute Order 113046, dated March 29, 2012, the commission adopted a resolution creating the Grand Parkway Transportation Corporation (GPTC) pursuant to Chapter 431 of the Transportation Code to assist in the development, financing, refinancing, design, construction, reconstruction, expansion, operation and/or maintenance of the SH 99 (Grand Parkway) toll project. In subsequent minute orders, the commission delegated responsibility to GPTC for the development, construction, financing, tolling, operation and maintenance of Segment D in Harris County and Segments E, F-1, F-2, G, H, I-1, and I-2 of the project. This minute order would designate Segment B-1 a toll project on the state highway system and extend all power and authority to GPTC to develop, finance, refinance, design, construct, reconstruct, expand, toll, operate, and/or maintain Segment B-1.

116626

116625

	8.	Prom	ulgatior	n of Administrative Rules Under Title 43, Texas Administrative Code,			
		and the Administrative Procedure Act, Government Code, Chapter 2001:					
		a.	Rule	Proposals			
116627			(1)	Chapter 9 - Contract and Grant Management			
				Amendments to §§9.11-9.12, §§9.15-9.18, §§9.23-9.25, and §9.27 concerning			
				contracts for highway projects (MO)			
				This minute order proposes amendments to department rules necessary to implement Senate Bill 1021, 88th Legislature, 2023, Regular Session, which allows bids on projects with an engineer's estimate of less than \$1 million to be opened and contracts awarded by the district engineer for highway improvement or the support services division director for building construction. Additionally, revisions are proposed to increase the threshold for projects where the highest level of bidder qualification may be waived, increase the minimum bidding capacities granted for the differing levels of bidder qualification, remove the requirement for bids opened at the state level to be read publicly, update Performance Review Committee rules regarding affiliates and appeal of			
				remedial action, and align the rules with current business practices.			
116628			(2)	Chapter 7 - Rail Facilities			
				The repeal of §§7.82, 7.83, and 7.86, enactment of new §§7.82, 7.83, and 7.86, and amendments to §§7.80, 7.84-7.85, 7.87-7.95, all concerning the Rail Fixed Guideway System State Safety Oversight Program (MO)			
				The proposed amendments incorporate required federal Infrastructure Investment and Jobs Act (IIJA) program elements into the state safety oversight program standard, including risk-based inspections, rail agency safety committees, training requirements, and public transportation agency safety plan content.			
116629			(3)	Chapter 31 - Public Transportation			
				Amendments to §§31.11 and 31.13 concerning State funding programs (MO) The proposed amendments revise state funding allocations of public transportation grant program funding to transit districts serving rural, small urban, and large urban areas. Amendments address 2020 Census changes to population and area designations throughout the state and incorporate increased appropriations from the 88th Legislature.			
		b.		Adoption			
116630			-	ter 16 - Planning and Development of Transportation Projects			
				dments to §16.105 (Unified Transportation Program) and §16.154 (Transportation ation Funding Formulas) (MO)			
				nendments modify certain definitions and formula allocations and provide exceptions to			
			carryo	ver that will help provide flexibility and optimize the use of federal funding in alignment deral requirements.			
	9.	Publi	c Trans	portation			
116631		Assoc	iation (
		Assista	ance Prog	tified in this minute order reflects the allocation of §5311(b)(3) Rural Transportation gram funds to the Texas Transit Association for the 2024 Texas Transit Association Annual ce, Expo, and Roadeo training activities.			

10. State Infrastructure Bank (Presentation)

Bell County - City of Nolanville - Consider an amendment to Minute Order 116493 to amend the maturity term and interest rate of the State Infrastructure Bank loan between the department and the city of Nolanville for a project for bridge repair, road construction, and a shared use path necessary for a non-tolled, off-system project to make improvements to Old Nolanville Road and bridge in Bell County, Texas (MO)

Minute Order 116493 authorized a State Infrastructure Bank loan to the city of Nolanville (city) for a term of seven years with an interest rate of 3.56%. The city has requested to have the maturity term of the loan changed to 15 years and subsequently, the interest rate will be changed to 4.08% to reflect the new maturity term of the loan.

11. Eminent Domain Proceedings

116633

116632

Various Counties - Consider the authorization of the filing of condemnation proceedings to acquire real property by eminent domain for non-controlled and controlled access highways (see attached itemized list) (MO)

Commission findings, determinations, and authorizations for the state, by motion made in accordance with Senate Bill 18 (82nd Legislature), to acquire by eminent domain, upon the payment of adequate and just compensation, various ownership interests in specific parcels of real property that are needed to develop or improve both non-controlled and controlled access state highways, to include requesting the state attorney general to bring and pursue condemnation suits relating to those specific parcels of real property described in the attached itemized list.

12. Routine Minute Orders and Reports

Donations to the Department

	а.	voliations to the Department				
116634		Farious Districts - Consider the acknowledgment of donations with a value of \$500 or hore, including donations of money, materials, services, or real property, that are made to the department for the purpose of assisting the department in carrying out its function and duties or for improving access to or from a highway on the state highway system (see tached itemized list) (<u>MO</u>) tate statutes require the commission to acknowledge the acceptance of a gift to the department that is valued at \$500 or more. By the adoption of this minute order, the commission cknowledges the receipt and acceptance of the property specified in the minute order.				
	b.	Real Estate Dispositions				
		he commission must approve the sales, transfers, and exchanges of state rights of way and ther real properties that are no longer needed for a state highway purpose. It must also approv ccept, and acknowledge donations to the state of real property that is valued at \$500 or more.				
116635		Fannin County - SH 121 - Consider an easement release to the underlying fee owner (MO) The district has determined that the easement is no longer needed for highway purposes				
		The easement may be released to the underlying fee owner.				
116636		Parker County - I-20 - Consider the sale of right of way to an abutting landowner (MO)				
		The district has determined that the land is no longer needed for highway purposes. An abutting landowner has requested to purchase the land, and it may be sold to the requester.				
116637		B) Travis County - RM 1431 - Consider the sale of right of way to Travis County, Texas (county) (MO)				
		The district has determined that the land is no longer needed for highway purposes. The county has requested to purchase the land, and it may be sold to the county.				

12. Routine Minute Orders and Reports (continued)

b. Real Estate Dispositions (continued)

(4) Wichita County - US 82 - Consider the sale of right of way to an abutting landowner (MO)

The district has determined that the land is no longer needed for highway purposes. An abutting landowner has requested to purchase the land, and it may be sold to the requester.

c. Reports

(1) **Compliance Division Report**

State law requires the commission to establish a compliance program, which must include a Compliance Division to oversee the program. The Compliance Division is responsible for acting to prevent and detect serious breaches of department policy, fraud, waste, and abuse of office, including any acts of criminal conduct within the department. The Compliance Division is required to provide a monthly report to the commission regarding investigations and a summary of information relating to trends and recommendations.

(2) Letting Allocation Status Report

Quarterly status report on the Fiscal Year 2024 letting allocation, the actual allocation utilized through the current month, and proposed remaining highway maintenance and construction contract letting for the fiscal year (Report) *This report will provide the current overall allocation status, by district, metropolitan planning organization, and statewide program, of the Fiscal Year 2024 letting allocation and will also provide the anticipated effect on the letting allocation of remaining proposed highway maintenance and construction letting.*

(3) Quarterly Cash Report

Quarterly report on Fiscal Year 2024 State Highway Fund 6 cash status (<u>Report</u>) This report updates the commission on the year-to-date cash balance and activity of State Highway Fund 6. The report will include original projections and actual revenues/inflows and expenditures/outflows on a cash basis.

(4) Annual Financial Report

Texas Department of Transportation Annual Comprehensive Financial Report (with Independent Auditor's Report) for the Fiscal Year Ended August 31, 2023 (Report)

State law requires that a state agency prepare an annual financial report regarding the agency's use of appropriated money during the preceding fiscal year. In addition, the department is required to have an independent certified public accountant audit the department's books and accounts for each toll project or system at least annually.

(5) **Texas Mobility Fund**

Audited financial statements of the Texas Mobility Fund as required by the governing master resolution (Report)

The master resolution governing the issuance of Texas Mobility Fund (TMF) bonds requires the preparation of an audited financial report of the TMF for each fiscal year. Audited financial statements have been prepared for Fiscal Year 2023.

(6) Central Texas Turnpike System

Travis and Williamson Counties - Audited financial statements of the Central Texas Turnpike System (CTTS), as required by the CTTS Indenture of Trust (Report)

The Indenture of Trust (Indenture) that prescribes the terms for bonds and obligations issued to finance the 2002 project of the Central Texas Turnpike System, a toll project comprised of the SH130, Segments 1-4, SH45N, SH45SE, and Loop 1 project elements, requires the preparation of a financial report of the results of operation of the system for each fiscal year. Audited financial statements meeting the requirements of the Indenture have been prepared for Fiscal Year 2023.

116638

	12.	Rout	ine Minute Orders and Reports (continued)
116639		d.	Economically Disadvantaged Counties Program (EDCP) 2023
			Various Counties - Consider the approval of the Fiscal Year 2023 Annual Report on the
			Economically Disadvantaged Counties Program (MO)
			State law requires the commission to provide an annual report on the Economically
			Disadvantaged Counties Program to the governor, the lieutenant governor, and the speaker of the
			House of Representatives. This report documents the use of matching funds and local incentives
			as well as the savings to counties participating in the program.
		e.	Speed Zones
116640			Various Counties - Consider the establishment or alteration of regulatory and
			construction speed zones on various sections of highways in the state (MO)
			This minute order establishes or alters regulatory and construction speed zones on various sections of highways in the state.
	13.		Executive Session Pursuant to Government Code, Chapter 551 Section 551.071 - Consultation with and advice from legal counsel regarding any item on
			Section 551.071 - Consultation with and advice from legal counsel regarding any field on

OPEN COMMENT PERIOD - At the conclusion of all other agenda items, the commission will allow an open comment period, not to exceed one hour, to receive public comment on any other matter that is under the jurisdiction of the department. No action will be taken. Each speaker will be allowed a maximum of three minutes. Speakers must be signed up prior to the beginning of the open comment period.

this agenda, pending or contemplated litigation, or other legal matters.

ADJOURN

* * *

NOTE:

Enumerated agenda items are assigned numbers for ease of reference and will not necessarily be considered by the commission in that order. Agenda items with (MO) are those for which the commission is considering an action.

<u>TEXAS TRANSPORTATION COMMISSION AGENDA</u> <u>Attached Lists</u> <u>January 17, 2024</u>

<u>Highway Improvement and Other Transportation Facilities</u> State Let (a)					
<u></u>	<u>County</u>	<u>Highway</u>	Controlling		
<u>Dist.</u>	<u>Name</u>	Number	Project No.		
ABL	HOWARD	SH 350	C 693-1-34		
ABL	SCURRY	FM 1673	BR 2024(664)		
ABL	SCURRY	US 180	F 2024(705)		
ABL	SHACKELFORD	FM 576	BR 2024(663)		
ADL	SHACKELFOND	1 ¹ 1 ¹ 1 ¹ J/0	DK 2024(003)		
AMA	DEAF SMITH	US 60	C 168-5-43		
AMA	HUTCHINSON	SH 136	F 2024(462)		
AMA	POTTER	US 60	BR 2024(520)		
	TOTTER	00 00	DR 202 ((320)		
ATL	CASS	US 59	C 218-3-94		
ATL	CASS	VA	C 919-00-85		
ATL	MORRIS	US 67	STP 2024(632)HES		
ATL	TITUS	SH 49	F 2024(645)		
AUS	BASTROP	SH 71	C 265-3-53		
AUS	HAYS	FM 2770	C 3210-1-20		
AUS	HAYS	RM 150	C 1197-1-25		
AUS	TRAVIS	RM 2769	C 2718-1-15		
AUS	TRAVIS	US 290	C 113-13-184		
AUS	TRAVIS	VA	STP 2024(597)VRU		
AUS	WILLIAMSON	FM 619	BR 2024(598)		
AUS	WILLIAMSON	IH 35	C 15-8-431		
1100		111.00			
BMT	CHAMBERS	IH 10	C 508-2-129		
BMT	JEFFERSON	SH 87	C 306-3-138		
BMT	TYLER	US 190	NH 2013(561)		
2	112211	0.0 170			
BWD	BROWN	US 67	С 54-7-90		
BWD	COLEMAN	US 84	С 54-3-27		
BWD	MILLS	US 84	C 54-8-27		
BRY	LEON	FM 745	STP 2023(206)TAPS		
BRY	ROBERTSON	US 79	STP 2024(610)VRU		
CHS	CHILDRESS	VA	C 925-00-80		
CHS	CHILDRESS	VA	C 925-00-93		
CHS	HARDEMAN	US 287	F 2024(638)		
		-~ -0,	((()))		
CRP	JIM WELLS	SH 141	C 383-3-24		
CRP	SAN PATRICIO	US 181	F 2024(689)		
		-~	(,		
DAL	COLLIN	US 75	F 2024(691)		
DAL	DALLAS	IH 45	F 2B23(093)		
			= ====(0,0)		

Italicized text in document is provided for informational purposes only and is not part of the official posted agenda

<u>Highway Improvement and Other Transportation Facilities (continued)</u> State Let (a)					
State Let (a)	<u>County</u>	<u>Highway</u>	<u>Controlling</u>		
Dist.	<u>Name</u>	<u>Number</u>	Project No.		
			C 92-14-108		
DAL	DALLAS	IH 45			
DAL	DENTON	IH 35E	C 196-1-118		
ELP	BREWSTER	SH 118	C 358-2-31		
ELP	CULBERSON	IH 10	F 2024(654)		
ELP	EL PASO	IH 10	F 2024(655)		
ELP	EL PASO	SH 20	STP 2024(606)HES		
ELP	HUDSPETH	SH 20	STP 2024(607)HES		
ELP	PRESIDIO	US 67	C 20-8-48		
ETW	JOHNSON	VA	STD 2024(622)VDI		
FTW			STP 2024(633)VRU		
FTW	SOMERVELL	US 67	STP 2024(345)HES		
HOU	FORT BEND	UA 90	C 27-8-182		
HOU	GALVESTON	FM 518	CM 2023(589)		
HOU	GALVESTON	VA	C 912-73-232		
HOU	HARRIS	BU 90-U	C 28-1-105		
HOU	HARRIS	US 90	C 28-2-99		
		VA			
HOU	HARRIS		F 2024(618)		
HOU	HARRIS	VA	C 912-72-749		
HOU	MONTGOMERY	VA	C 912-37-252		
HOU	WALLER	FM 362	C 523-2-51		
LRD	WEBB	FM 1472	STP 2024(702)HES		
LBB	LUBBOCK	CS	BR 2024(658)		
LBB	YOAKUM	US 380	C 297-1-14		
LDD	IGAROW	05 560	0 2)7-1-14		
LFK	HOUSTON	SH 21	F 2024(613)		
ODA	MIDLAND	CS	BR 2B23(292)		
ODA	MIDLAND	SL 250	C 1188-2-118		
ODA	MIDLAND	SL 250	C 1100-2-110		
PAR	DELTA	SH 19	STP 2024(417)HES		
PAR	FRANKLIN	SH 37	C 189-5-51		
PAR	HUNT	SH 34	F 2024(637)		
חנוס	CAMEDON	CII 40			
PHR	CAMERON	SH 48	STP 2024(690)HES		
PHR	CAMERON	SL 499	C 1137-2-42		
PHR	HIDALGO	FM 1925	F 2024(623)		
PHR	KENEDY	US 77	F 2024(529)		
PHR	STARR	US 83	F 2024(695)		
SJT	TOM GREEN	CS	STP 2023(406)VRU		
SJT	TOM GREEN	US 87	STP 2024(725)HES		
SJT	TOM GREEN	US 87	STP 2024(725)HES		
J J I		0007	511 202 4 (0 <i>59</i>)1125		

Italicized text in document is provided for informational purposes only and is not part of the official posted agenda

<u>Highway Improvement and Other Transportation Facilities (continued)</u> <u>State Let (a)</u>					
<u>State Let (u)</u>	<u>County</u>	<u>Highway</u>	Controlling		
<u>Dist.</u>	<u>Name</u>	Number	Project No.		
SAT	BEXAR	FM 2696	STP 2024(534)HES		
SAT	FRIO	IH 35	C 17-6-86		
SAT	KENDALL	SH 27	C 142-6-29		
SAT	WILSON	SH 27 SH 123	F 2024(696)		
5/11	WIESON	511 125	1 2024(0)0)		
TYL	GREGG	US 259	C 392-3-53		
TYL	HENDERSON	SH 19	STP 2024(630)HES		
TYL	RUSK	US 79	C 206-7-59		
TYL	SMITH	VA	STP 2024(629)VRU		
TYL	WOOD	US 69	C 203-5-47		
112	11000	0.0 0)			
WAC	HILL	FM 2959	C 3030-1-10		
WAC	HILL	SH 171	C 418-2-35		
WAC	MCLENNAN	CS	STP 2024(653)HES		
			()		
WFS	THROCKMORTON	SH 79	C 284-2-27		
WFS	WICHITA	SS 447	F 2024(665)		
			· · · ·		
YKM	COLORADO	SH 71	BR 2024(817)		
YKM	DEWITT	CR	BR 2B22(011)		
YKM	FAYETTE	US 77	F 2024(576)		
YKM	GONZALES	SH 80	C 287-3-34		
YKM	VICTORIA	US 59	F 2024(584)		
YKM	VICTORIA	US 77	F 2024(643)		
Routine Main	tenance				
State Let (b)					
	<u>County</u>	<u>Highway</u>	Controlling		
Dist.	<u>Name</u>	Number	Project No.		
AMA	CARSON	US 60	MMC - 646155001		
AMA	GRAY	US 60	RMC - 646177001		
AMA	MOORE	US 87	MMC - 646156001		
AMA	MOORE	US 287	RMC - 639332001		
ATL	HARRISON	US 80	RMC - 645381001		
AUS	BASTROP	SH 21	MMC - 640887001		
AUS	BLANCO	US 281	MMC - 640893001		
BMT	JEFFERSON	US 69	RMC - 645893001		
BWD	EASTLAND	IH 20	RMC - 646068001		
BRY	BRAZOS	SH 6	MMC - 646095001		
CRP	KARNES	FM 627	RMC - 646050001		
CRP	KLEBERG	US 77	RMC - 646186001		

Italicized text in document is provided for informational purposes only and is not part of the official posted agenda Page 9

<u>Routine Maintenance (continued)</u> State Let (b)					
<u></u>	<u>County</u>	Highway	Controlling		
<u>Dist.</u>	Name	Number	Project No.		
CRP	NUECES	SH 286	BPM - 646071001		
CRP	NUECES	US 77	RMC - 644799001		
CIU	NULCLS	0577	INVIC - 044777001		
DAL	COLLIN	US 75	RMC - 644991001		
DAL	COLLIN	US 75	RMC - 645615001		
DAL	COLLIN	US 380	RMC - 644989001		
DAL	DALLAS	IH 30	RMC - 643172001		
DAL	DENTON	FM 407	RMC - 644879001		
DAL	DENTON	FM 1171	RMC - 645703001		
DAL	DENTON	IH 35E	RMC - 644875001		
DAL	ELLIS	IH 35E IH 35E	RMC - 644827001		
DAL	ELLIS	IH 35E IH 35E	RMC - 644837001		
DAL	ELLIS		KIVIC - 044037001		
ELP	BREWSTER	US 90	RMC - 645177001		
FTW	TARRANT	IH 820	RMC - 645281001		
HOU	FORT BEND	FM 1236	RMC - 642590001		
HOU	FORT BEND	US 59	RMC - 645476001		
HOU	GALVESTON	FM 518	RMC - 645943001		
HOU	HARRIS	IH 69	RMC - 645709001		
HOU	HARRIS	SH 249	RMC - 645037001		
HOU	HARRIS	SL 8	RMC - 645575001		
HOU	HARRIS	SL 8	RMC - 645647001		
HOU	MONTGOMERY	IH 45	RMC - 645021001		
HOU	WALLER	FM 3318	RMC - 642227001		
noe	WILLER	1 1 1 3510	ICIVIC - 042227001		
LRD	MAVERICK	US 277	RMC - 645235001		
LFK	HOUSTON	US 287	RMC - 646042001		
LFK	POLK	US 59	RMC - 644957001		
	TOLK	0000	Rule 011957001		
ODA	PECOS	IH 10	RMC - 642816001		
SAT	ATASCOSA	IH 37	RMC - 646168001		
SAT	COMAL	SH 46	RMC - 645789001		
SAT	FRIO	IH 35	RMC - 646169001		
TYL	SMITH	SL 323	RMC - 645397001		
WAC	BELL	SH 36	RMC - 645271001		
WAC	BELL	SL 363	RMC - 645907001		
WAC	BOSQUE	SH 6	MMC - 644388001		
WAC	MCLENNAN	US 84	MMC - 644380001		
W110					

Construction and Rehabilitation of Buildings				
<u>State Let (c)</u>				
D .	<u>County</u>	<u>Site</u>		
<u>Dist.</u>	<u>Name</u>	<u>Number</u>	<u>Project ID</u>	
AMA	POTTER	049562	04-47042013	32
AUS	TRAVIS	149720	14-47042450	08
BRY	BRAZOS	179043	17-38042138	39
BRY	WASHINGTON	179001	17-38042132	20
CRP	NUECES	169904	16-38042131	18
ELP	EL PASO	249671	241859-23-0	01
ELP	EL PASO	249887	381859-24-0	01
LBB	LUBBOCK	059576	051859-24-0	01
LBB	LUBBOCK	059576	381859-05-2	4-02
LFK	HOUSTON	119671	111859-23-0	
ODA	ECTOR	068064	388710-23-0	
PHR	CAMERON	219005	21-38042132	
YKM	DEWITT	139074	131859-24-0	
Eminent Dom	nain			
Non-Controll				
County	Highway	<u>Exhibit</u>	ROW CSJ No.	Parcel
Angelina	US 69	269	0200-01-096	P00065651
Angelina	US 69	245	0200-01-096	P00065657
Angelina	US 69	246	0200-01-096	P00065660
Angelina	US 69	277	0200-01-096	P00065661
Angelina	US 69	310	0200-01-096	P00065662
Angelina	US 69	278	0200-01-096	P00065664
Angelina	US 69	272	0200-01-096	P00065665
Angelina	US 69	275	0200-01-096	P00065666
Angelina	US 69	279	0200-01-096	P00065667
Brazoria	SH 6	266	0192-02-061	1
Brazoria	SH 6	265	0192-02-061	2
Brazoria	FM 518	23	0976-02-097	207
Brazos	FM 158	276	0212-03-064	16
Collin	SS 399	306	0047-10-004	P00069741
Collin	SS 399	78	0047-10-004	P00069751
Collin	SS 399	308	0047-10-004	P00069768.001002
Collin	SS 399	307	0047-10-004	P00069776
Collin	US 380	129	0135-02-072	P00069662.001
Collin	US 380 US 380	129	0135-02-072	P00069663.001002E
Collin	US 380	128	0135-02-072	P00069664.001,002E,.003E
Collin	US 380	123	0135-02-072	P00069665.001

122

121

120

119

118

117

116

0135-02-072

0135-02-072

0135-02-072

0135-02-072

0135-02-072

0135-02-072

0135-02-072

P00069666.001

P00069667.001

P00069668.001

P00069673.001

P00069674.001

P00069675.001

P00069670.001-.002E

Collin

Collin

Collin

Collin

Collin

Collin

Collin

US 380

Eminent Doma		X.		
	<u>d Access (continued</u> Highway	<u>)</u> Exhibit	ROW CSJ No.	Parcel
<u>County</u> Collin	US 380	<u>Exilipit</u> 115	0135-02-072	<u>P00069676.001</u>
Collin	US 380	113	0135-02-072	P00069677.001
Collin	US 380	114	0135-02-072	P00069678.001
Collin	US 380	113	0135-02-072	P00069679.001
Collin	US 380	112	0135-02-072	P00069680.001
Collin	US 380 US 380	111	0135-02-072	P00069681.001
Collin	US 380 US 380	109	0135-02-072	P00069681.001 P00069682.001
Collin	US 380 US 380	109	0135-02-072	P00069683.001
	US 380 US 380	108	0135-02-072	P00069683.001 P00069684.001
Collin Collin	US 380 US 380	107	0135-02-072	P00069684.001 P00069685.001
				P00069685.001 P00069686.001
Collin	US 380	105	0135-02-072	
Collin	US 380	104	0135-02-072	P00069687.001
Collin	US 380	103	0135-02-072	P00069688.001
Collin	US 380	102	0135-02-072	P00069689.001
Collin	US 380	101	0135-02-072	P00069690.001
Collin	US 380	100	0135-02-072	P00069691.001
Collin	US 380	99	0135-02-072	P00069692.001
Collin	US 380	98 97	0135-02-072	P00069693.001
Collin	US 380	97	0135-02-072	P00069694.001
Collin	US 380	96	0135-02-072	P00069695.001
Collin	US 380	95	0135-02-072	P00069696.001
Collin	US 380	94	0135-02-072	P00069697.001
Collin	US 380	93	0135-02-072	P00069698.001
Collin	US 380	92	0135-02-072	P00069699.001
Collin	US 380	91	0135-02-072	P00069700.001
Collin	US 380	180	0135-02-074	P000074455.001002
Collin	US 380	178	0135-02-074	P00074379
Collin	US 380	177	0135-02-074	P00074380
Collin	US 380	176	0135-02-074	P00074382
Collin	US 380	175	0135-02-074	P00074383
Collin	US 380	174	0135-02-074	P00074384
Collin	US 380	173	0135-02-074	P00074385
Collin	US 380	172	0135-02-074	P00074386
Collin	US 380	171	0135-02-074	P00074387
Collin	US 380	170	0135-02-074	P00074388
Collin	US 380	169	0135-02-074	P00074389
Collin	US 380	168	0135-02-074	P00074390
Collin	US 380	167	0135-02-074	P00074392
Collin	US 380	166	0135-02-074	P00074393.001003
Collin	US 380	165	0135-02-074	P00074394
Collin	US 380	164	0135-02-074	P00074395
Collin	US 380	163	0135-02-074	P00074396
Collin	US 380	162	0135-02-074	P00074397
Collin	US 380	161	0135-02-074	P00074398
Collin	US 380	160	0135-02-074	P00074400
Collin	US 380	159	0135-02-074	P00074401
Collin	US 380	158	0135-02-074	P00074402
Collin	US 380	150	0135-02-074	P00074403
Collin	US 380	156	0135-02-074	P00074404
20mm	0.000	100		100071101

Italicized text in document is provided for informational purposes only and is not part of the official posted agenda P = 12

Eminent Dom	<u>ain</u> ed Access (continued	I)		
<u>County</u>	Highway	<u>D</u> Exhibit	ROW CSJ No.	Parcel
Collin	US 380	<u>155</u>	0135-02-074	P00074405.001002
Collin	US 380	154	0135-02-074	P00074406
Collin	US 380	153	0135-02-074	P00074408
Collin	US 380	247	0135-02-074	P00074409
Collin	US 380	149	0135-02-074	P00074410
Collin	US 380	148	0135-02-074	P00074411
Collin	US 380	179	0135-02-074	P00074412.001002
Collin	US 380	152	0135-02-074	P00074413
Collin	US 380	152	0135-02-074	P00074414
Collin	US 380	147	0135-02-074	P00074415
Collin	US 380	146	0135-02-074	P00074417
Collin	US 380	145	0135-02-074	P00074418
Collin	US 380	321	0135-02-074	P00074420
Collin	US 380	323	0135-02-074	P00074421
Collin	US 380	325	0135-02-074	P00074422.001002
Collin	US 380	323	0135-02-074	P00074423
Collin	US 380	144	0135-02-074	P00074424
Collin	US 380	328	0135-02-074	P00074425
Collin	US 380 US 380	372	0135-02-074	P00074425
Collin	US 380	409	0135-02-074	P00074427
Collin	US 380 US 380	143	0135-02-074	P00074427 P00074428
Collin	US 380 US 380	143	0135-02-074	P00074428 P00074429
Collin	US 380 US 380	142	0135-02-074	P00074429 P00074430
Collin	US 380 US 380	141	0135-02-074	P00074430 P00074431
Collin	US 380 US 380	140	0135-02-074	P00074431 P00074432
Collin	US 380 US 380	132	0135-02-074	P00074432 P00074433
Collin	US 380 US 380	329	0135-02-074	P00074435
Collin	US 380 US 380	330	0135-02-074	P00074435 P00074436
Collin	US 380 US 380	331	0135-02-074	P00074430 P00074437
Collin	US 380 US 380	332	0135-02-074	P00074437 P00074438
Collin	US 380 US 380	334	0135-02-074	P00074438 P00074441
Collin	US 380 US 380	335	0135-02-074	P00074441 P00074442
Collin Collin	US 380	336 337	0135-02-074 0135-02-074	P00074443 P00074444
Collin	US 380 US 380	338	0135-02-074	P00074444 P00074445
Collin				P00074443 P00074446
Collin	US 380	339	0135-02-074 0135-02-074	P00074448 P00074448
	US 380	340	0135-02-074	P00074448 P00074449
Collin	US 380	341		
Collin	US 380	342	0135-02-074	P00074450
Collin	US 380	343	0135-02-074	P00074451
Collin	US 380	344	0135-02-074	P00074452
Collin	US 380	345	0135-02-074	P00074453
Collin	US 380	346	0135-02-074	P00074454
Collin	US 380	376	0135-02-074	P00074457
Collin	US 380	347	0135-02-074	P00074458
Collin	US 380	235	0135-04-039	P00072848
Collin	US 380	234	0135-04-039	P00072849
Collin	US 380	233	0135-04-039	P00072852
Collin	US 380	232	0135-04-039	P00072854

Eminent Domai				
	Access (continued)		DOW COLN	
<u>County</u>	<u>Highway</u>	<u>Exhibit</u>	ROW CSJ No.	Parcel
Collin	US 380	231	0135-04-039	P00072856
Collin	US 380	229	0135-04-039	P00072860
Collin	US 380	228	0135-04-039	P00072861
Collin	US 380	227	0135-04-039	P00072862
Collin	US 380	226	0135-04-039	P00072863
Collin	US 380	225	0135-04-039	P00072864.001002
Collin	US 380	224	0135-04-039	P00072865
Collin	US 380	223	0135-04-039	P00072866
Collin	US 380	222	0135-04-039	P00072867
Collin	US 380	219	0135-04-039	P00072868.001002
Collin	US 380	218	0135-04-039	P00072869
Collin	US 380	217	0135-04-039	P00072870
Collin	US 380	215	0135-04-039	P00072871
Collin	US 380	213	0135-04-039	P00072872
Collin	US 380	210	0135-04-039	P00072873
Collin	US 380	208	0135-04-039	P00072874
Collin	US 380	205	0135-04-039	P00072875
Collin	US 380	202	0135-04-039	P00072876.001002
Collin	US 380	199	0135-04-039	P00072877
Collin	US 380	195	0135-04-039	P00072878
Collin	US 380	230	0135-04-039	P00072857
Collin	US 380	239	0135-05-031	P00072908
Collin	US 380	238	0135-05-031	P00072909
Collin	US 380	237	0135-05-031	P00072910
Collin	US 380	236	0135-05-031	P00072911
Collin	US 380	282	0135-11-027	P00067908.001
Collin	US 380	283	0135-11-027	P00067909.001002
Collin	US 380	284	0135-11-027	P00067910.001
Collin	US 380	281	0135-11-027	P00067911.001,.002E,.003
Collin	US 380	425	0135-11-027	P00067912.001,.002E,.003
Collin	US 380	424	0135-11-027	P00067913.001
Collin	US 380	423	0135-11-027	P00067914.001
Collin	US 380	422	0135-11-027	P00067915.001
Collin	US 380	421	0135-11-027	P00067916.001
Collin	US 380	420	0135-11-027	P00067917.001
Collin	US 380	419	0135-11-027	P00067918.001
Collin	US 380	418	0135-11-027	P00067919.001
Collin	US 380	417	0135-11-027	P00067920.001
Collin	US 380	416	0135-11-027	P00067921.001
Collin	US 380	415	0135-11-027	P00067922.001
Collin	US 380	406	0135-11-027	P00067923.001
Collin	US 380	75	0135-11-027	P00067924.001
Collin	US 380	280	0135-11-027	P00067925.001
Collin	US 380	150	0135-11-027	P00067926.001
Collin	US 380	274	0135-15-003	P00068385.001, .002
Collin	US 380	273	0135-15-003	P00068391.001
Collin	US 380	273	0135-15-003	P00068392.001
Collin	US 380	270	0135-15-003	P00068417.001
Collin	US 380	268	0135-15-003	P00068419.001

Non-Controlled Access (continued) Exhibit ROW CSJ No. Parcel Collin US 380 267 0135-15-003 P00068420.001 Collin US 380 264 0135-15-003 P00073321.001 Collin US 380 353 0135-15-003 P00074465 Collin US 380 354 0135-15-003 P00074467.001-00 Collin US 380 356 0135-15-003 P00074467.001-00 Collin US 380 357 0135-15-003 P00074467.001-00 Collin US 380 357 0135-15-003 P00074470 Collin US 380 360 0135-15-003 P00074471 Collin US 380 361 0135-15-003 P00074472 Collin US 380 362 0135-15-003 P00074473 Collin US 380 362 0135-15-003 P00074476 Collin US 380 365 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074481 <	Eminent Dom		I)		
Collin US 380 267 0135-15-003 P00068445.001 Collin US 380 264 0135-15-003 P00073321.001 Collin US 380 353 0135-15-003 P00074464 Collin US 380 353 0135-15-003 P00074465 Collin US 380 355 0135-15-003 P00074465 Collin US 380 356 0135-15-003 P00074467.00100 Collin US 380 356 0135-15-003 P00074467 Collin US 380 359 0135-15-003 P00074470 Collin US 380 361 0135-15-003 P00074471 Collin US 380 361 0135-15-003 P00074472 Collin US 380 364 0135-15-003 P00074474 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074480				ROW CSJ No	Parcel
Collin US 380 264 0135-15-003 P00064845.001 Collin US 380 352 0135-15-003 P00073321.001 Collin US 380 354 0135-15-003 P00074464 Collin US 380 355 0135-15-003 P00074465 Collin US 380 355 0135-15-003 P00074468 Collin US 380 357 0135-15-003 P00074469 Collin US 380 358 0135-15-003 P00074470 Collin US 380 360 0135-15-003 P00074471 Collin US 380 361 0135-15-003 P00074472 Collin US 380 362 0135-15-003 P00074473 Collin US 380 364 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074481 Collin US 380 367 0135-15-003 P00074483 <td< td=""><td></td><td></td><td></td><td></td><td></td></td<>					
Collin US 380 352 0135-15-003 P00073321.001 Collin US 380 353 0135-15-003 P00074465 Collin US 380 355 0135-15-003 P00074465 Collin US 380 356 0135-15-003 P00074467.00100 Collin US 380 356 0135-15-003 P00074469 Collin US 380 358 0135-15-003 P00074470 Collin US 380 359 0135-15-003 P00074470 Collin US 380 361 0135-15-003 P00074472 Collin US 380 361 0135-15-003 P00074473 Collin US 380 364 0135-15-003 P00074475 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074482 Collin US 380 367 0135-15-003 P00074482					
Colin US 380 353 0135-15-003 P00074464 Collin US 380 354 0135-15-003 P00074467.00100 Collin US 380 356 0135-15-003 P00074467.00100 Collin US 380 357 0135-15-003 P00074467.00100 Collin US 380 358 0135-15-003 P00074470 Collin US 380 360 0135-15-003 P00074471 Collin US 380 361 0135-15-003 P00074473 Collin US 380 362 0135-15-003 P00074473 Collin US 380 363 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074481 Collin US 380 367 0135-15-003 P00074481 Collin US 380 371 0135-15-003 P00074483 <					
Collin US 380 354 0135-15-003 P00074465 Collin US 380 355 0135-15-003 P00074468 Collin US 380 357 0135-15-003 P00074468 Collin US 380 357 0135-15-003 P00074470 Collin US 380 359 0135-15-003 P00074471 Collin US 380 360 0135-15-003 P00074471 Collin US 380 361 0135-15-003 P00074473 Collin US 380 363 0135-15-003 P00074474.001-00 Collin US 380 364 0135-15-003 P00074477 Collin US 380 366 0135-15-003 P00074477 Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074482 Collin US 380 370 0135-15-003 P00074482					
Collin US 380 355 0135-15-003 P00074467.001-00 Collin US 380 356 0135-15-003 P00074468 Collin US 380 357 0135-15-003 P00074470 Collin US 380 359 0135-15-003 P00074471 Collin US 380 360 0135-15-003 P00074472 Collin US 380 361 0135-15-003 P00074472 Collin US 380 362 0135-15-003 P00074477 Collin US 380 363 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074480 Collin US 380 366 0135-15-003 P00074481 Collin US 380 367 0135-15-003 P00074483 Collin US 380 371 0135-15-003 P00074483 Collin US 380 371 0135-15-003 P00074483.001-00					
Collin US 380 356 0135-15-003 P00074468 Collin US 380 357 0135-15-003 P00074470 Collin US 380 359 0135-15-003 P00074470 Collin US 380 360 0135-15-003 P00074471 Collin US 380 360 0135-15-003 P00074473 Collin US 380 362 0135-15-003 P00074475 Collin US 380 363 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074480 Collin US 380 366 0135-15-003 P00074481 Collin US 380 368 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074485.001-00. Collin US 380 371 0135-15-003 P00074485.001-00. Collin US 380 373 0135-15-003 P00074485.001-00.					
Collin US 380 357 0135-15-003 P00074469 Collin US 380 358 0135-15-003 P00074470 Collin US 380 360 0135-15-003 P00074471 Collin US 380 361 0135-15-003 P00074472 Collin US 380 362 0135-15-003 P00074475 Collin US 380 362 0135-15-003 P00074475 Collin US 380 366 0135-15-003 P00074475 Collin US 380 366 0135-15-003 P00074481 Collin US 380 367 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074483 Collin US 380 370 0135-15-003 P00074480 Collin US 380 371 0135-15-003 P00074480 Collin US 380 373 0135-15-003 P00074489.001-00					
Collin US 380 358 0135-15-003 P00074470 Collin US 380 359 0135-15-003 P00074471 Collin US 380 360 0135-15-003 P00074473 Collin US 380 361 0135-15-003 P00074476 Collin US 380 362 0135-15-003 P00074476 Collin US 380 364 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074480 Collin US 380 366 0135-15-003 P00074481 Collin US 380 367 0135-15-003 P00074482 Collin US 380 370 0135-15-003 P00074485.001-00 Collin US 380 371 0135-15-003 P00074485.001-00 Collin US 380 373 0135-15-003 P00074485.001-00 Collin US 380 374 0135-15-003 P00074490.001-00					
Collin US 380 359 0135-15-003 P00074471 Collin US 380 360 0135-15-003 P00074472 Collin US 380 362 0135-15-003 P00074473 Collin US 380 362 0135-15-003 P00074475 Collin US 380 363 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074477 Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074483 Collin US 380 369 0135-15-003 P00074483 Collin US 380 370 0135-15-003 P00074483 Collin US 380 371 0135-15-003 P00074480 Collin US 380 373 0135-15-003 P00074480 Collin US 380 373 0135-15-003 P00074480 Collin US 380 377 0135-15-003 P00074490 Collin<					
Collin US 380 360 0135-15-003 P00074472 Collin US 380 361 0135-15-003 P00074473 Collin US 380 362 0135-15-003 P00074475 Collin US 380 363 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074480 Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074481 Collin US 380 369 0135-15-003 P00074482 Collin US 380 370 0135-15-003 P00074483 Collin US 380 371 0135-15-003 P00074486 Collin US 380 371 0135-15-003 P00074486 Collin US 380 373 0135-15-003 P00074492 01-00 Collin US 380 377 0135-15-003 P00074494 02<					
Collin US 380 361 0135-15-003 P00074473 Collin US 380 362 0135-15-003 P00074474.001-00. Collin US 380 363 0135-15-003 P00074476 Collin US 380 364 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074481 Collin US 380 369 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074480 Collin US 380 371 0135-15-003 P00074480 Collin US 380 371 0135-15-003 P00074486 Collin US 380 373 0135-15-003 P00074491 Collin US 380 374 0135-15-003 P00074493 Collin US 380 377 0135-15-003 P00074494 <td< td=""><td></td><td></td><td></td><td></td><td></td></td<>					
Collin US 380 362 0135-15-003 P00074474.001002 Collin US 380 363 0135-15-003 P00074475 Collin US 380 364 0135-15-003 P00074476 Collin US 380 366 0135-15-003 P00074477 Collin US 380 366 0135-15-003 P00074480 Collin US 380 366 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074482 Collin US 380 370 0135-15-003 P00074483 Collin US 380 371 0135-15-003 P00074485.001002 Collin US 380 373 0135-15-003 P00074486 Collin US 380 373 0135-15-003 P00074496 Collin US 380 373 0135-15-003 P00074491 Collin US 380 375 0135-15-003 P00074494 Collin US 380 377 0135-15-003 P00074494					
Collin US 380 363 0135-15-003 P00074475 Collin US 380 364 0135-15-003 P00074476 Collin US 380 365 0135-15-003 P00074477 Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074481 Collin US 380 369 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074483 Collin US 380 370 0135-15-003 P00074484.001-000 Collin US 380 371 0135-15-003 P00074480.001-000 Collin US 380 373 0135-15-003 P00074480.001-000 Collin US 380 373 0135-15-003 P00074490.001-000 Collin US 380 374 0135-15-003 P00074492.001-00 Collin US 380 375 0135-15-003 P00074492.001-00 Collin US 380 377 0135-15-003 P000744					
Collin US 380 364 0135-15-003 P00074476 Collin US 380 365 0135-15-003 P00074477 Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074481 Collin US 380 368 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074482. Collin US 380 370 0135-15-003 P00074485.001-00. Collin US 380 371 0135-15-003 P00074485.001-00. Collin US 380 373 0135-15-003 P00074485.001-00. Collin US 380 373 0135-15-003 P00074496 Collin US 380 374 0135-15-003 P00074492.001-00. Collin US 380 375 0135-15-003 P00074492.001-00. Collin US 380 377 0135-15-003 P00074492.001-00. Collin US 380 377 0135-15-003 P000					
Collin US 380 365 0135-15-003 P00074477 Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074481 Collin US 380 368 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074483. Collin US 380 370 0135-15-003 P00074485.001-00. Collin US 380 371 0135-15-003 P00074485.001-00. Collin US 380 373 0135-15-003 P00074485.001-00. Collin US 380 373 0135-15-003 P00074489.001-00. Collin US 380 374 0135-15-003 P00074492.001-00. Collin US 380 375 0135-15-003 P00074492.001-00. Collin US 380 377 0135-15-003 P00074494 Collin US 380 377 0135-15-003 P00074494 Collin US 380 381 0135-15-003 P000					
Collin US 380 366 0135-15-003 P00074480 Collin US 380 367 0135-15-003 P00074481 Collin US 380 368 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074483 Collin US 380 370 0135-15-003 P00074485.001-000 Collin US 380 371 0135-15-003 P00074486.001-000 Collin US 380 373 0135-15-003 P00074489.001-000 Collin US 380 373 0135-15-003 P00074492.001-000 Collin US 380 374 0135-15-003 P00074492.001-000 Collin US 380 377 0135-15-003 P00074491 Collin US 380 377 0135-15-003 P00074494 Collin US 380 378 0135-15-003 P00074494 Collin US 380 379 0135-15-003 P00074494 Collin US 380 381 0135-15-003 P00074494 <td></td> <td></td> <td></td> <td></td> <td></td>					
Collin US 380 367 0135-15-003 P00074481 Collin US 380 368 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074483 Collin US 380 370 0135-15-003 P00074484.001-000 Collin US 380 371 0135-15-003 P00074485.001-000 Collin US 380 408 0135-15-003 P00074480.001-000 Collin US 380 373 0135-15-003 P00074489.001-000 Collin US 380 374 0135-15-003 P00074492.001-000 Collin US 380 375 0135-15-003 P00074492 Collin US 380 377 0135-15-003 P00074494 Collin US 380 377 0135-15-003 P00074494 Collin US 380 378 0135-15-003 P00074494 Collin US 380 379 0135-15-003 P00074496 Collin US 380 381 0135-15-003 P00074496 <td></td> <td></td> <td></td> <td></td> <td></td>					
Collin US 380 368 0135-15-003 P00074482 Collin US 380 369 0135-15-003 P00074483 Collin US 380 370 0135-15-003 P00074484.001-000 Collin US 380 371 0135-15-003 P00074485.001-000 Collin US 380 408 0135-15-003 P00074489.001-000 Collin US 380 373 0135-15-003 P00074489.001-000 Collin US 380 374 0135-15-003 P00074492.001-000 Collin US 380 377 0135-15-003 P00074493 Collin US 380 377 0135-15-003 P00074494 Collin US 380 377 0135-15-003 P00074494 Collin US 380 377 0135-15-003 P00074494 Collin US 380 378 0135-15-003 P00074494 Collin US 380 381 0135-15-003 P00074498 Collin US 380 382 0135-15-003 P00074500 <td></td> <td></td> <td></td> <td></td> <td></td>					
Collin US 380 369 0135-15-003 P00074483 Collin US 380 370 0135-15-003 P00074484.001003 Collin US 380 371 0135-15-003 P00074485.001003 Collin US 380 408 0135-15-003 P00074485.001003 Collin US 380 373 0135-15-003 P00074489.001003 Collin US 380 374 0135-15-003 P00074493 Collin US 380 374 0135-15-003 P00074493 Collin US 380 377 0135-15-003 P00074493 Collin US 380 377 0135-15-003 P00074494 Collin US 380 378 0135-15-003 P00074494 Collin US 380 378 0135-15-003 P00074496 Collin US 380 378 0135-15-003 P00074497 Collin US 380 381 0135-15-003 P00074496 Collin US 380 382 0135-15-003 P00074501					
Collin US 380 370 0135-15-003 P00074484.001-000 Collin US 380 371 0135-15-003 P00074485.001-000 Collin US 380 373 0135-15-003 P00074486 Collin US 380 373 0135-15-003 P00074489.001-000 Collin US 380 374 0135-15-003 P00074492.001-000 Collin US 380 374 0135-15-003 P00074492.001-000 Collin US 380 375 0135-15-003 P00074493 Collin US 380 377 0135-15-003 P00074494 Collin US 380 377 0135-15-003 P00074494 Collin US 380 378 0135-15-003 P00074494 Collin US 380 378 0135-15-003 P00074494 Collin US 380 381 0135-15-003 P00074499 Collin US 380 382 0135-15-003 P00074500 Collin US 380 383 0135-15-003 P00074503 <td></td> <td></td> <td></td> <td></td> <td></td>					
Collin US 380 371 0135-15-003 P00074485.001003 Collin US 380 408 0135-15-003 P00074486 Collin US 380 373 0135-15-003 P00074489.001003 Collin US 380 137 0135-15-003 P00074491 Collin US 380 374 0135-15-003 P00074492.001003 Collin US 380 377 0135-15-003 P00074493 Collin US 380 377 0135-15-003 P00074494 Collin US 380 377 0135-15-003 P00074496 Collin US 380 379 0135-15-003 P00074496 Collin US 380 379 0135-15-003 P00074496 Collin US 380 381 0135-15-003 P00074498 Collin US 380 382 0135-15-003 P00074499 Collin US 380 382 0135-15-003 P00074501 Collin US 380 384 0135-15-003 P00074503					
Collin US 380 408 0135-15-003 P00074486 Collin US 380 373 0135-15-003 P00074489.001002 Collin US 380 137 0135-15-003 P00074491 Collin US 380 374 0135-15-003 P00074492.001002 Collin US 380 377 0135-15-003 P00074493 Collin US 380 377 0135-15-003 P00074494 Collin US 380 377 0135-15-003 P00074494 Collin US 380 378 0135-15-003 P00074496 Collin US 380 379 0135-15-003 P00074497 Collin US 380 380 0135-15-003 P00074497 Collin US 380 381 0135-15-003 P00074498 Collin US 380 382 0135-15-003 P00074501 Collin US 380 383 0135-15-003 P00074502 Collin US 380 385 0135-15-003 P00074504					
CollinUS 3803730135-15-003P00074489.001003CollinUS 3801370135-15-003P00074491CollinUS 3803740135-15-003P00074492.001003CollinUS 3803750135-15-003P00074493CollinUS 3803770135-15-003P00074494CollinUS 3803770135-15-003P00074494CollinUS 3803780135-15-003P00074496CollinUS 3803790135-15-003P00074497CollinUS 3803800135-15-003P00074499CollinUS 3803810135-15-003P00074499CollinUS 3803820135-15-003P00074500CollinUS 3803820135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074504CollinUS 3803860135-15-003P00074504CollinUS 3803860135-15-003P00074505CollinUS 3803870135-15-003P00074506CollinUS 3803890135-15-003P00074509CollinUS 3803900135-15-003P00074509CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803920135-15-003<					
CollinUS 3801370135-15-003P00074491CollinUS 3803740135-15-003P00074492.001000CollinUS 3803750135-15-003P00074493CollinUS 3803770135-15-003P00074494CollinUS 3803780135-15-003P00074496CollinUS 3803790135-15-003P00074497CollinUS 3803790135-15-003P00074497CollinUS 3803800135-15-003P00074499CollinUS 3803810135-15-003P00074499CollinUS 3803820135-15-003P00074500CollinUS 3803820135-15-003P00074501CollinUS 3803830135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074509CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074509CollinUS 3803930135-15-003P00074509CollinUS 3803930135-15-003P00074509CollinUS 3803930135-15-003P					
CollinUS 3803740135-15-003P00074492.001003CollinUS 3803750135-15-003P00074493CollinUS 3803770135-15-003P00074494CollinUS 3803780135-15-003P00074496CollinUS 3803790135-15-003P00074497CollinUS 3803790135-15-003P00074497CollinUS 3803800135-15-003P00074499CollinUS 3803810135-15-003P00074499CollinUS 3803820135-15-003P00074500CollinUS 3803820135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074506CollinUS 3803890135-15-003P00074506CollinUS 3803900135-15-003P00074506CollinUS 3803910135-15-003P00074508CollinUS 3803920135-15-003P00074509CollinUS 3803920135-15-003P00074511CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802160135-15-003P					
CollinUS 3803750135-15-003P00074493CollinUS 3803770135-15-003P00074494CollinUS 3803780135-15-003P00074496CollinUS 3803790135-15-003P00074497CollinUS 3803800135-15-003P00074498CollinUS 3803810135-15-003P00074499CollinUS 3803810135-15-003P00074499CollinUS 3803820135-15-003P00074500CollinUS 3803830135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074502CollinUS 3803860135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074504CollinUS 3803870135-15-003P00074506CollinUS 3803890135-15-003P00074506CollinUS 3803910135-15-003P00074508CollinUS 3803920135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3803930135-15-003P00074512CollinUS 3802160135-15-003P00074513CollinUS 3802140135-15-003P00074514<					
CollinUS 3803770135-15-003P00074494CollinUS 3803780135-15-003P00074496CollinUS 3803790135-15-003P00074497CollinUS 3803800135-15-003P00074498CollinUS 3803810135-15-003P00074499CollinUS 3803820135-15-003P00074500CollinUS 3803820135-15-003P00074501CollinUS 3803830135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803860135-15-003P00074505CollinUS 3803870135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802140135-15-003P00074514					
CollinUS 3803780135-15-003P00074496CollinUS 3803790135-15-003P00074497CollinUS 3803800135-15-003P00074498CollinUS 3803810135-15-003P00074499CollinUS 3803820135-15-003P00074500CollinUS 3803830135-15-003P00074501CollinUS 3803830135-15-003P00074502CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803860135-15-003P00074505CollinUS 3803870135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802160135-15-003P00074513CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803790135-15-003P00074497CollinUS 3803800135-15-003P00074498CollinUS 3803810135-15-003P00074499CollinUS 3803820135-15-003P00074500CollinUS 3803830135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803840135-15-003P00074503CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803860135-15-003P00074505CollinUS 3803870135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802160135-15-003P00074513CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803800135-15-003P00074498CollinUS 3803810135-15-003P00074500CollinUS 3803820135-15-003P00074501CollinUS 3803830135-15-003P00074502CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074505CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803810135-15-003P00074499CollinUS 3803820135-15-003P00074500CollinUS 3803830135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074505CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803820135-15-003P00074500CollinUS 3803830135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074505CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803830135-15-003P00074501CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074505CollinUS 3803870135-15-003P00074506CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803840135-15-003P00074502CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074505CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803850135-15-003P00074503CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074505CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803920135-15-003P00074511CollinUS 3803930135-15-003P00074512CollinUS 3802160135-15-003P00074513CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803860135-15-003P00074504CollinUS 3803870135-15-003P00074505CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803870135-15-003P00074505CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803880135-15-003P00074506CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803890135-15-003P00074507CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803900135-15-003P00074508CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3803910135-15-003P00074509CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514	Collin				
CollinUS 3803920135-15-003P00074510CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514	Collin	US 380			P00074508
CollinUS 3803930135-15-003P00074511CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514					
CollinUS 3802160135-15-003P00074512CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514				0135-15-003	
CollinUS 3802140135-15-003P00074513CollinUS 3802120135-15-003P00074514	Collin	US 380	393	0135-15-003	P00074511
Collin US 380 212 0135-15-003 P00074514	Collin	US 380	216	0135-15-003	P00074512
	Collin	US 380	214	0135-15-003	P00074513
C-11: LIC 200 211 0125 15 002 D00074515	Collin	US 380	212	0135-15-003	P00074514
Comm US 380 211 U135-15-003 P000/4515	Collin	US 380	211	0135-15-003	P00074515
Collin US 380 209 0135-15-003 P00074516	Collin	US 380	209	0135-15-003	P00074516

Italicized text in document is provided for informational purposes only and is not part of the official posted agenda

Eminent Domain				
Non-Controlled Ac		F-1.91.94	DOW COLN-	Denvel
<u>County</u>	Highway	Exhibit	<u>ROW CSJ No.</u>	Parcel
Collin	US 380 US 380	207 206	0135-15-003 0135-15-003	P00074518 P00074519
Collin		200		
Collin	US 380		0135-15-003	P00074520
Collin	US 380	203	0135-15-003	P00074521
Collin	US 380	138	0135-15-003	P00074522
Collin	US 380	139	0135-15-003	P00074525
Collin	US 380	136	0135-15-003	P00074526
Collin	US 380	201	0135-15-003	P00074527
Collin	US 380	200	0135-15-003	P00074528
Collin	US 380	198	0135-15-003	P00074529
Collin	US 380	197	0135-15-003	P00074530
Collin	US 380	196	0135-15-003	P00074531
Collin	US 380	194	0135-15-003	P00074532
Collin	US 380	193	0135-15-003	P00074533.001002
Collin	US 380	192	0135-15-003	P00074534
Collin	US 380	135	0135-15-003	P00074536
Collin	US 380	191	0135-15-003	P00074537
Collin	US 380	190	0135-15-003	P00074538
Collin	US 380	189	0135-15-003	P00074539
Collin	US 380	188	0135-15-003	P00074540
Collin	US 380	187	0135-15-003	P00074541
Collin	US 380	186	0135-15-003	P00074542
Collin	US 380	185	0135-15-003	P00074543
Collin	US 380	184	0135-15-003	P00074544
Collin	US 380	134	0135-15-003	P00074545
Collin	US 380	133	0135-15-003	P00074547
Collin	US 380	183	0135-15-003	P00074548
Collin	US 380	182	0135-15-003	P00074549
Collin	US 380	313	0135-15-003	P00074550
Collin	US 380	181	0135-17-003	P00072883
Collin	US 380	241	0135-17-003	P00072886
Collin	US 380	309	0135-17-003	P00072887
Collin	US 380	304	0135-17-003	P00072888
Collin	US 380	240	0135-17-003	P00072892
Collin	US 380	242	0135-17-003	P00072893
Collin	US 380	255	0135-17-003	P00072894
Collin	US 380	257	0135-17-003	P00072895
Collin	US 380	256	0135-17-003	P00072896
Collin	US 380	258	0135-17-003	P00072897.001002
Collin	US 380	259	0135-17-003	P00072898
Collin	US 380	305	0135-17-003	P00072899
Collin	US 380	263	0135-17-003	P00072900
Collin	US 380	243	0135-17-003	P00072904
Collin	FM 1461	414	1973-01-018	34
Collin	FM 1461 FM 1461	414	1973-01-018	38
Collin	FM 1461 FM 1461	261	1973-01-018	P00075146
Collin	FM 1401 FM 428	351	2678-01-015	P00075140 P00067648.001
Collin	FM 428	333	2678-01-015	P00067649.001003
		333 21	2678-01-015	P00067650.001003 P00067650.001002
Collin	FM 428	$\angle 1$	20/0-01-013	r 0000/030.001002

Eminent Domain				
	Access (continued)			
<u>County</u>	<u>Highway</u>	<u>Exhibit</u>	ROW CSJ No.	Parcel
Collin	FM 428	407	2678-01-015	P00067651.001
Collin	FM 428	20	2678-01-015	P00067652.001
Collin	FM 428	410	2678-01-015	P00067653.001
Collin	FM 428	350	2678-01-015	P00067654.001
Collin	FM 428	22	2678-01-015	P00067655.001
Dallas	SL 9	317	2964-10-007	P00071868
Dallas	SL 9	314	2964-10-007	P00071869
Dallas	SL 9	315	2964-10-007	P00071870
Dallas	SL 9	316	2964-10-007	P00071871
Dallas	SL 9	322	2964-10-007	P00071873
Dallas	SL 9	324	2964-10-007	P00071874
Dallas	SL 9	326	2964-10-007	P00071875
Dallas	SL 9	399	2964-10-007	P00071876
Dallas	SL 9	400	2964-10-007	P00071877
Dallas	SL 9	77	2964-10-007	P00071878
Dallas	SL 9	401	2964-10-007	P00071879
Dallas	SL 9	402	2964-10-007	P00071880
Dallas	SL 9	403	2964-10-007	P00071881
Dallas	SL 9	404	2964-10-007	P00071882
Dallas	SL 9	76	2964-10-007	P00071886
Dallas	SL 9	405	2964-10-007	P00071944
Denton	US 377	85	0081-06-043	P00024384
Denton	US 377	87	0081-06-043	P00024400
Denton	US 377	86	0081-06-043	P00024401
Denton	US 377	90	0081-06-043	P00024402
Denton	US 377	286	0081-06-043	P00024412
Denton	US 377	287	0081-06-043	P00024414
Denton	US 377	288	0081-06-043	P00024415
Denton	US 377	289	0081-06-043	P00024417
Denton	US 377	290	0081-06-043	P00024418
Denton	US 377	291	0081-06-043	P00024421
Denton	US 377	292	0081-06-043	P00024422
Denton	US 377	293	0081-06-043	P00024429
Denton	US 377	294	0081-06-043	P00024430E
Denton	US 377	295	0081-06-043	P00024431E
Denton	US 377	84	0081-06-043	P00024454, P00024454E
Denton	US 377	89	0081-06-043	P00024501
Denton	US 377	88	0081-06-043	P00024513
Denton	US 377	262	0081-06-043	P00024631
Denton	US 380	127	0135-10-067	P00067706.001
Denton	US 380	126	0135-10-067	P00067707.001003E
Denton	US 380	125	0135-10-067	P00067708.001
Denton	US 380	124	0135-10-067	P00067709.001
Denton	FM 407	319	1310-01-052	P00068110
Galveston	FM 646	285	0978-02-072	416
Galveston	FM 646	398	0978-02-073	404
Galveston	FM 646	300	0978-02-073	422
Gregg	SH 31	46	0424-02-049	P00067252.001
Gregg	SH 31	44	0424-02-049	P00067253.001
51-00	NII 01			200007200.001

Eminent Domain				
Non-Controlled Ac	<u>cess (continued)</u>			
<u>County</u>		<u>Exhibit</u>	ROW CSJ No.	Parcel
Gregg	SH 31	45	0424-02-049	P00067268.001
Gregg	SH 31	412	0424-02-049	P00067269.001
Gregg	SH 31	36	0424-02-049	P00067278.001
Gregg	SH 31	37	0424-02-049	P00067279.001
Gregg	SH 31	40	0424-02-049	P00067280.001
Gregg	SH 31	38	0424-02-049	P00067281
Gregg	SH 31	39	0424-02-049	P00067283.001
Gregg	SH 31	41	0424-02-049	P00067284.001
Gregg	SH 31	43	0424-02-049	P00067289.001
Gregg	SH 31	42	0424-02-049	P00067310.001
Gregg	SL 485	312	3290-02-011	P00061570.001
Gregg	SL 485	348	3290-02-011	P00061572.001
Gregg	SL 485	349	3290-02-012	P00061577.001
Harris	SH 35	303	0178-09-030	109
Harris	SH 35	302	0178-09-030	111
Harris	SH 35	301	0178-09-030	117
Hidalgo	FM 2061	395	1939-01-066	1
Hidalgo	FM 2061	396	1939-01-066	10
Hidalgo	FM 2061	397	1939-01-066	19
Hidalgo	FM 2061	19	1939-01-066	52
Hidalgo	FM 2061	18	1939-01-066	59
Hidalgo	FM 2061	17	1939-01-066	74
Hidalgo	FM 2061	16	1939-01-066	99
Hidalgo	FM 2061	10	1939-01-066	108
Hidalgo	FM 2061	13	1939-01-066	118
Hidalgo	FM 2061	12	1939-01-066	120
Hidalgo	FM 2061	15	1939-01-066	127
Hidalgo	FM 2061	13	1939-01-066	128
Hidalgo	FM 2061	11	1939-01-066	130
Hunt	US 380	221	0135-06-040	P00072913
Hunt	US 380	220	0135-06-040	P00072914
Karnes	BUS HWY 181E	1	0348-04-062	P00063461.001
Kaufman	FM 741	34	1092-01-023	P00056551.001
Kaufman	FM 741	33	1092-01-023	P00056566.001
Kaufman	FM 741	32	1092-01-023	P00056570.001
Kaufman	FM 741	31	1092-01-023	P00056571.001
Kaufman	FM 741	28	1092-01-023	P00056590
Kaufman	FM 741	28 27	1092-01-023	P00056593
Kaufman	FM 741	26	1092-01-023	P00056595
Kaufman	FM 741	20 30	1092-01-023	P00056596
Kaufman	FM 741	30 25	1092-01-023	P00056637.001
Kaufman	FM 741	23 29	1092-01-023	P00056655
Kaufman			1092-01-023	
	FM 741	24		P00056661
Lampasas	US 183	82 83	0272-06-041	P00071472.001
Lampasas	US 183	83 81	0272-06-041	P00071473.001
Lampasas	US 183	81	0272-06-041	P00071478.001
Lampasas Liberta	US 183	80 248	0272-06-042	P00071461.001
Liberty Liberty	SH 105	248	0338-05-034	800
Liberty	SH 105	249	0338-05-034	801

Italicized text in document is provided for informational purposes only and is not part of the official posted agenda

Eminent Domain				
Non-Controlled A	ccess (continued)			
<u>County</u>	<u>Highway</u>	<u>Exhibit</u>	ROW CSJ No.	Parcel
Liberty	SH 105	250	0338-05-034	802
Liberty	SH 105	253	0338-05-034	803
Liberty	SH 105	251	0338-05-034	804
Liberty	SH 105	252	0338-05-034	805
Liberty	SH 105	254	0338-05-034	806
Montgomery	FM 1488	260	0523-07-003	11
Montgomery	FM 1488	394	0523-07-003	17
Montgomery	FM 1488	9	0523-07-003	19
Montgomery	FM 1488	8	0523-07-003	22
Montgomery	FM 1488	7	0523-07-003	23
Montgomery	FM 1488	3	0523-07-003	24
Montgomery	FM 1488	6	0523-07-003	25
Montgomery	FM 1488	2	0523-07-003	27
Montgomery	FM 1488	5	0523-07-003	26A
Montgomery	FM 1488	4	0523-07-003	26B
Montgomery	SH 242	35	3538-01-047	300
Nacogdoches	US 259	311	0138-06-050	P00065760
Nueces	FM 665	296	1052-02-099	P00074660.001
Nueces	FM 665	297	1052-02-099	P00074661.001
Robertson	US 79	320	0204-09-052	4
Smith	SH 31	62	0424-01-060	P00067166.001
Smith	SH 31	56	0424-01-060	P00067172.001
Smith	SH 31	55	0424-01-060	P00067179.001
Smith	SH 31	70	0424-01-060	P00067180.001
Smith	SH 31	47	0424-01-060	P00067181.001
Smith	SH 31	69	0424-01-060	P00067182.001
Smith	SH 31	68	0424-01-060	P00067183.001
Smith	SH 31	57	0424-01-060	P00067184.001
Smith	SH 31	58	0424-01-060	P00067185.001
Smith	SH 31	48	0424-01-060	P00067186.001
Smith	SH 31	59	0424-01-060	P00067187.001
Smith	SH 31	49	0424-01-060	P00067189.001
Smith	SH 31	67	0424-01-060	P00067190.001
Smith	SH 31	60	0424-01-060	P00067192.001
Smith	SH 31	71	0424-01-060	P00067193.001
Smith	SH 31	61	0424-01-060	P00067199.001
Smith	SH 31	64	0424-01-060	P00067200.001
Smith	SH 31	72	0424-01-060	P00067201.001
Smith	SH 31	50	0424-01-060	P00067204.001
Smith	SH 31	65	0424-01-060	P00067205.001
Smith	SH 31	51	0424-01-060	P00067206.001
Smith	SH 31	52	0424-01-060	P00067207.001
Smith	SH 31	66	0424-01-060	P00067208.001
Smith	SH 31	53	0424-01-060	P00067209.001
Smith	SH 31	63	0424-01-060	P00067210.001002
Smith	SH 31	73	0424-01-060	P00067212.001.001003
Smith	SH 31	54	0424-01-060	P00067216.001
Smith	SH 31	74	0424-01-060	P00067218.001
Smith	FM 756	298	0492-04-040	P00063768.001
			• •	

Eminent Domain				
Non-Controlled A	<u>ccess (continued)</u>	F 194	DOW/ COLN	ъ
<u>County</u>	Highway	Exhibit	<u>ROW CSJ No.</u>	Parcel
Smith Smith	FM 756	299 426	0492-04-040	P00063793.001 P00063838.001
	FM 756	426	0492-04-044	
Taylor	US 83	244	0034-01-138	P00070082
Wharton	US 59	318	0089-07-165	303 D00005566
Wichita	US 82	79	0156-04-124	P00005566
Wichita	US 82	411	0156-04-124	P00005567
Eminent Domain Controlled Access				
County	<u>Highway</u>	<u>Exhibit</u>	ROW CSJ No.	Parcel
Burnet	US 281	I	0252-01-086	P00059545
Burnet	US 281	Н	0252-01-086	P00059546
Burnet	US 281	F	0252-01-086	P00059547
Burnet	US 281	G	0252-01-086	P00059548
Collin	US 380	K	0135-02-072	P00069669.001
Collin	US 380	J	0135-02-072	P00069672.001
Denton	IH 35E	P	0196-01-100	2
Denton	IH 35E	Q	0196-01-100	3
Denton	IH 35E	Š	0196-01-100	5
Denton	IH 35E	R	0196-01-100	4,4AC
Ellis	IH 45	M	0092-04-083	P00072644
Ellis	IH 45	L	0092-05-059	P00072609
Ellis	IH 45	Ŷ	0092-05-059	P00072611
Ellis	IH 45	X	0092-05-059	P00072613
Ellis	IH 45	W	0092-05-059	P00072614
Ellis	IH 45	V	0092-05-059	P00072618
Ellis	IH 45	Ż	0092-05-059	P00072619
Ellis	IH 45	BB	0092-05-059	P00072628
Ellis	IH 45	JJ	0092-05-059	P00072629
Ellis	IH 45	HH	0092-05-059	P00072630
Ellis	IH 45	GG	0092-05-059	P00072632
Gregg	IH 15 IH 20	II	0495-07-085	P00064923.001
Harris	IH 20 IH 69	D	0027-13-227	118
Harris	IH 69	E	0027-13-227	119
Harris	IH 45	A	0500-03-608	302
Harris	IH 45 IH 45	B	0500-03-608	318
Harris	IH 45 IH 45	C	0500-03-608	322
Harris	IH 45 IH 45	CC	0500-03-608	439
Harris	III 45 IH 45	FF	0500-03-608	404AAQ
Harris	III 45 IH 45	U	0500-08-002	719
Harris	III 45 IH 45	DD	0500-08-002	502AAQ
Travis	IH 45 IH 35	0	0015-13-434	P00064470
Travis	IH 35 IH 35	AA	0015-13-434	P00064480
Travis	IH 35 IH 35	EE	0015-13-434	P00064504
Travis	IH 35 IH 35	EE N	0015-13-434	P00067422
	IH 35 IH 35	N T	0015-13-433	P00087422 P0074688
Travis	111 33	1	0013-13-443	100/4000

<u>Donations to the Departm</u> <u>Donor</u>	Dist	<u>County</u>	Donation Description
3405 Xpress LLC	AUS	Williamson	Design and construction of shoulder widening and re-striping of a section of FM 3405 to accommodate a new left turn lane deceleration, a new right turn lane deceleration, and driveway access to Lot 1, Block A of the north US 183 and FM 3405 Phase 1 Subdivision in Liberty Hill.
Aguilas Robles, LLC	SAT	Comal	The installation of a traffic signal at FM 1102 and Watson Road in Comal County, Texas.
Artavia Development Company	HOU	Montgomery	Design and construction of a traffic signal from north, south, east, and west bound FM 1314 into the Artavia development in Conroe.
Bell County Expo, Incorporated dba Cadence Bank Center	WAC	Bell	Funds to replace the Bell County Expo Center exit signs with Cadence Bank Center signs on I-35 and I-14 in Belton.
Belton Real Estate LLC	WAC	Bell	Design and construction of modifying the ramp and I-35 southbound frontage road to prevent direct access to Laila Street intersection in Belton.
Blue Ridge Commerce Center West LLC	HOU	Fort Bend	Design and construction of a deceleration lane, street tie-in, and traffic signal from eastbound and westbound FM 2234 into the Blue Ridge Commerce Center West development in Houston.
BW Texas Bryan Nash, LLC	BRY	Brazos	Design and construction of the fourth leg of a traffic signal and a shared use path on FM 158 at Nash Street adjacent to the donor's property located in Bryan.
CanAm 1604, LLC	SAT	Bexar	Design and construction for the installation of a left turn lane on FM 2252 located approximately 0.27 miles northeast of Loop 1604 and FM 2252 intersection in San Antonio.
Cedar Creek MH, LLC	AUS	Bastrop	Design and construction of two deceleration lanes on SH 71 0.02 miles west of County Road 214 and on SH 71 2.97 miles east from Triangle Acres Lane in Cedar Creek.
Cerco Development, Inc.	AUS	Travis	Design and construction of a traffic signal on US 290 and Ledgestone Terrace in Austin.

Donations to the Department (continued)				
Donor CSW South Lamar MF, LP	<u>Dist</u> AUS	<u>County</u> Travis	Donation Description Design and construction of a mountable curb and delineation along the exit ramp of US 290 to Loop 343 South Lamar Boulevard. in Austin.	
CT II Partners LP	HOU	Harris	Design and construction of a right turn lane from northbound SH 288 into the CT II Partners Ltd development in Houston.	
Essence Prep, Inc.	SAT	Bexar	Funds to cover the design and construction of a southbound-northbound turnaround on I-410 frontage road at the intersection with US 87 (Rigsby Avenue) in the San Antonio.	
KDAveO, LLC	WAC	Bell	Design and construction of a right turn lane from northbound I-35 frontage road onto River View Road in Belton.	
Lennar Homes of Texas Land and Construction, Ltd.	SAT	Bexar	Design and construction for installation of westbound to eastbound turnaround, eastbound to westbound turnaround, two right turn lanes, grading, and drainage on US 181 located approximately 975 feet north of West Laguna Road to 165 feet north of Dove Road Bexar County.	
Martin Marietta Materials, Inc.	TRF	Jack Wise	Funds to design, fabricate, and install two memorial highway designation signs on the portion of US 380 between US 281 and County Road 3001, designated as the Lost Battalion Memorial Highway within Jack and Wise Counties.	
Precast/Prestressed Concrete Institute	BRG	N/A	Airfare, ground transportation, lodging at the hotel, meals, and other directly related expenses for Taya Retterer, Transportation Engineer, and Jason Tucker, Structural Materials Section Director to attend the 2024 PCI Convention Days held on February 6-9, 2024, in Denver.	
QT South, LLC	LRD	Webb	Funds for a portion of the state's cost of an installation of a proposed traffic signal and associated roadway improvements near the intersection of Business 59- Z and Loop 20 in Laredo.	
RH Pioneer North, LLC	AUS	Travis	Design and construction of four westbound deceleration lanes along FM 734 from Samsung Boulevard to Yager Lane/Hulsey Road intersections in Austin.	

Donations to the Depart	Donations to the Department (continued)					
<u>Donor</u> Sig Magnolia LP	<u>Dist</u> HOU	<u>County</u> Montgomery	Donation Description Design and construction of a right turn lane from southbound FM 1486 into the Magnolia Springs development in Montgomery.			
Texas DPS Troopers Foundation, Inc.	TRF	Bowie	Funds to design, fabricate, and install two memorial highway designation signs on the portion of US 67 within the municipal limits of Texarkana, designated as the Trooper Howard Jordan Memorial Highway within Bowie County.			
Texas DPS Troopers Foundation, Inc.	TRF	Denton	Funds to design, fabricate, and install two memorial highway designation signs on the portion of US 377 within the municipal limits of Denton, designated as the Trooper Hollis S. Lacy Memorial Highway within Denton County.			
Texas DPS Troopers Foundation, Inc.	TRF	Howard	Funds design, fabricate, and install two memorial highway designation signs on the portion of I-20 between mile marker 173 and mile marker 190, designated as the Trooper Troy Hogue Memorial Highway within Howard County.			
The Redeemed Christian Church of God (Desire of Nations)	HOU	Galveston	Design and construction of a right turn lane from northbound SH 3 into the Desire of Nations Redeemed Christian Church of God in League City.			
Union Pacific Railroad Company	ELP	El Paso	Remaining grade separation credit, which represents the real estate agreed value from the Loop 375 Border Highway West Extension Project in El Paso.			
Woodmere Development Co., Ltd.	HOU	Harris	Design and construction of a street tie-in from east bound SH 99 at Beckendorff Road into the Grand Mason development in Houston.			
Yisrael Realty (Bergstrom Logistics Center Austin) Limited Partnership	AUS	Travis	Funds to design and construction of new traffic signals at the intersection of SH 130 frontage roads with Elroy Road and Pearce Lane in Austin.			
Evangeline Cafe	AUS	Travis	Revenue generation through the Sponsor a Highway Program. This is a contract renewal on an existing sign location.			
Presidio Doors	AUS	Travis	Revenue generation through the Sponsor a Highway Program. This is a contract renewal on an existing sign location.			

Donations to the Departn	Donations to the Department (continued)				
Donor Sport Clips, Inc.	<u>Dist</u> AUS	<u>County</u> Travis	Donation Description Revenue generation through the Sponsor a Highway Program. This is a contract renewal on an existing sign location.		
Elephant Insurance Services, LLC	DAL	Collin	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.		
Elephant Insurance Services, LLC	DAL	Dallas	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.		
Elephant Insurance Services, LLC	DAL	Denton	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.		
Law Firm of Roger "Rocky" Walton, P.C.	FTW	Tarrant	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.		
Dysol Inc. dba Socomore	FTW	Wise	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.		
AMOCO Federal Credit Union	HOU	Harris	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.		
Daniel Lopez dba Clever Solutions	HOU	Harris	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.		
Elephant Insurance Services, LLC	HOU	Harris	Litter pick-up throughout a corridor on the State's right of way through the Sponsor a Highway Program.		